Your OASE UVC is reliable. All models are thoroughly tested and most of them have proven themselves over many years. We are so convinced of their performance that we are offering an additional guarantee promise with our OASE Clear Water Guarantee.*(P. 310)

UVC bulbs are certainly subject to natural wear. After approx. 8000 operating hours (Bitron Eco bulbs 12000 h), they no longer generate sufficient UVC performance. When this is the case it is time to replace the bulb.





The matter is quite clear

How to find your matching UVC REPLACEMENT BULBS:



UVC replacement bulb		Item no.	. Vitronic					Bitron													
3	UVC 5 W	57110																			
	UVC 7 W	57111																			
The second	UVC 9 W	54984																			
	UVC 11 W	56112	•																		
() P	UVC 15 W	53770						•													
	UVC 18 W	56236		•					•												
The	UVC 24 W	56237			•					•											
Tho	UVC 25 W	53969									•										
	UVC 36 W	55432				•						•		••							
VI.	UVC 55 W	56636					•						•		••				•		
VII.	UVC Eco 60 W	57077														••	•••	••			



Recommendation

Only with OASE UVC replacement bulbs can you be one hundred percent certain that your UVC device will also continue to develop the full capacity.

- Guaranteed service life of 8000 operating hours (Bitron Eco 12000 h)
- Best possible UVC output power in combination with ballast device and quartz glass
- Quality-tested safety for a long device service life
- Optimal fit for your OASE device
- Maintains the quarantee requirements

Original OASE UVC replacement bulbs guarantee performance on the very first day. In addition, they sustainably assure the requirements of the Clear Water Guarantee.*(P.310) Naturally, the device guarantee applies here as well. Unfortunately, again and again we are confronted with supposedly inexpensive bulbs from third-party vendors. Often these have deviating dimensions and do not fit in the bulb socket or in the

quartz glass. Or they only maintain the specified performance for a short period of time. Because such bulbs can have unforeseeable effects on the UVC devices, particularly the ballast device and internal components, if such bulbs are used, unfortunately the device guarantee will also be rendered null and void. We ask for your understanding in this regard.

HOW TO FIND YOUR MATCHING UVC REPLACEMENT BULBS:



UVC replacement bulb Item no.		Filt	ral	BioPress			FiltoClear								BioSmart			FiltoMatic				
ove replacement bails		item no.	Tireia		Dioriess						Tintoclear					Diosiliait			1 111		.10	
UVO	∕C 7W	57111	•		•											•						
UVO	∕C 9 W	54984				•		•									•					
UVO	/C 11 W	56112		•			•		•	•		•						•	•			
UVO	/C 18 W	56236									•									•		
UVO	∕C 24 W	56237											•								•	
UVO	∕C 36 W	55432												•								
UVO	/C 55 W	56636													•							